

Dangerous and Recalled Products Transmittal Form, Third Quarter 2008									
<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>13.8V DC Power Supplies</b>	The recalled power supplies are wired incorrectly, posing electrocution and fire hazards	Consumers should unplug the recalled power supply immediately and take it to any RadioShack store for a free repair. Registered owners of the recalled power supplies will be mailed a notice.	The recall involves RadioShack 13.8V DC Power Supplies, catalog numbers 22-507 and 22-508 with date codes from 08A04 through 01A08. Date code format is MMYY where MM is the month and YY is the year. The catalog number and date code are located on the back of the power supply. Power Supplies with a green dot on the product and the product's packaging have already been repaired and are not included in the recall.	RadioShack Corp., of Fort Worth, Texas	October 2004 through January 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08319.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08319.html</a>			
<b>SunRingle Hollow Quick Release Devices for Bicycles</b>	The quick release devices can unexpectedly fail or break when locked in position on the bicycle, causing the rider to lose control, which poses a serious fall hazard.	Consumers should stop riding bicycles with the recalled quick release devices immediately, remove the quick release device and bring it to their local bike dealer or retailer for a free inspection and replacement	This recall involves the SunRingle Hollow Quick Release Devices for bicycles and includes models Hollow CroMo Front 100mm, Hollow CroMo Rear 130mm, and Hollow CroMo Rear 135mm. These devices have hollow skewers. They were sold individually or with SunRingle front and rear wheels with model names Black Flag, Disc o Flea, Charger, STR8 Track, Accelerator R3.00C and Accelerator T3.0C. "Ringle" is stamped on the lever. Quick release devices with a solid skewer are not included in this recall.	Hayes Bicycle Group, of Mequon, Wis.	June 2007 through May 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08321.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08321.html</a>			
<b>Outdoor Canopies</b>	The canopies fail to comply with a voluntary flammability standard could pose a fire hazard to consumers	Consumers should stop using the canopy and contact Wanda Technology for instructions on how to return it for a full refund. Consumers with the recalled outdoor canopies are being contacted by the firm.	This recall involves the outdoor canopies with "Code Number: 1020-8-WT2007". The canopies are white, measure 10' X 20', and have a metal frame with four corner posts that support a fabric top which shields the user from the sun. The code number can be found on a label sewn into the canopy fabric.	Wanda Technology Inc, of Santa Ana, Calif.	January 2008 through May 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08592.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08592.html</a>			
<b>Honda Lawn Mowers</b>	The lawn mower's rear shield can break off allowing debris to be thrown toward the operator, which poses a laceration hazard to consumers.	Consumers should immediately stop using the recalled lawn mowers and contact their local Honda Lawn and Garden dealer to schedule a free repair. Registered owners of the recalled lawn mowers have been contacted by direct mail notification	This recall involves HRX walk-behind lawn mowers with model numbers HRX217(K)2HXA and HRX217(K)2HMA. The model and serial number are printed on a label located on the upper rear of the mower deck. Serial numbers included in the recall are MAGA-1500001 through 1520532. The recalled lawn mowers are red with "HONDA" written on the bag.	American Honda Motor Corp., of Torrance, Calif.	October 2007 to June 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08328.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08328.html</a>			

<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>Conversion Underground Propane Storage Tanks</b>	An odorant is added to propane to help alert customers to propane leaks, but rust inside a propane tank can cause the odor to fade. Some converted above-ground to underground converted tanks can have an increased susceptibility to odor fade, causing consumers to be unable to detect the odor of propane in the event of a gas leak. This can pose a fire and burn hazard to consumers if there is a leak in the propane gas system.	Necessary repairs will be performed at the tank by the retail propane company. Known retail propane companies that sold the recalled tanks have been notified directly of the recall and will contact consumers directly.	The recall includes 120 gallon to 1,000 gallon underground propane storage tanks which were previously converted from above-ground to underground storage tanks in the period of January 2005 through April 2008.	American Welding & Tank LLC, of Jesup, Ga	January 2005 through April 2008.	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08594.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08594.html</a>			
<b>Bench Scale Adapters</b>	The recalled bench scale adapters can smoke, catch fire and melt, posing a fire hazard to consumers.	Consumers should immediately stop using the adapters and return them to American Weigh Scales for a credit towards the purchase of another product, or to receive a replacement adapter. Replacement adapters will be black in color. American Weigh Scales will reimburse consumers for shipping and handling charges on returns.	The recalled bench adapters are silver colored. "MINI CHARGER" is printed on the back of the adapter. When plugged in a red light shines through a blue plastic piece on the outer side of the adapter. "AC Adapter" is printed on a white label on the inner side. The adapters are used with bench scale model AMW-13, AMW-1000, AMW-2000, and AMW-500i.	American Weigh Scales, of Charleston, S.C.	February 2008 through March 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08330.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08330.html</a>			
<b>Model Year 2007-2008 TRX 420 Rancher ATVs</b>	If the ATV's rubber CV (constant velocity) boots get punctured or torn the joint will become contaminated and severe binding of the CV joints could occur, resulting in the sudden loss of steering control. This poses a risk of injury or death to riders.	Consumers should immediately stop using these recalled ATVs and contact any Honda ATV dealer to make an appointment for a free repair. Registered owners of the recalled ATVs have been sent direct notices	This recall involves Model Year 2007-08 Honda TRX420 ATVs, also known as the Honda FourTrax Rancher 4X4. These are adult-size ATVs designed for use by riders age 16 and older. The recalled ATVs are available in red, black, olive, and camouflage. The Honda name and wing logo are printed on the fuel tank. The model year is printed on a label located on the frame behind the left front wheel. The model name "Rancher" is on a label at the left rear of the ATV.	American Honda Motor Co. Inc., of Torrance, Calif.	January 2007 through May 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08595.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08595.html</a>			
<b>TV Stands</b>	The stability of the stand does not meet industry standards to prevent TV tip-over, posing a risk of injury or death to consumers	Consumers should immediately remove the TV from stand and contact Studio RTA to receive a free repair kit.	This recall involves "Silhouette" TV stands with black or brushed silver and black frames and three glass shelves. Models included in the recall are 403650 (brushed silver and black) and 404191 (black). Model numbers are printed on the packaging and instruction sheet.	Studio RTA, of Pico Rivera, Calif.	September 2007 through June 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08331.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08331.html</a>			
<b>Engines used in SpeeCo and Huskee Brand Log Splitters</b>	The engine's fuel tank can crack and leak, posing a risk of fire or explosion.	Consumers should immediately stop using the affected log splitters and contact any Honda Lawn and Garden dealer or Honda Engine dealer for a free repair. Registered owners of the recalled log splitters will be mailed a notice.	The recall involves Honda engines (model type GCV160LA N1A) used in Split Master by SpeeCo and Huskee brand log splitters. Only engine serial numbers between 5547012 and 6880908 are included in the recall. The serial number is located below the upper shroud near the oil dipstick	American Honda Motor Corp., of Torrance, Calif.	January 2007 through June 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08332.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08332.html</a>			

<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>SLA90 Youth All-Terrain Vehicles (ATVs)</b>	The youth ATV lacks front brakes, a manual fuel shut-off, and padding to cover the sharp edges on the handlebar assembly. Additionally, the vehicle is sold without a tire pressure gauge or adequate flag pole bracket. The defects could lead to young drivers losing control of the ATVs, which poses the risk of serious injuries or death.	Consumers should immediately stop using these ATVs and contact SunL Group for instructions on how to receive a full refund	The recalled SLA90 ATVs are intended for children between the ages of 12 and 15 years old. The recalled SLA90 ATVs were available in the following solid colors: red, blue, yellow, green. The ATVs were available in the following camo colors: pink, brown, green, and blue. The word "Sunl" is on the front side of the ATV	SunL Group Inc., of Irving, Texas	May 2005 through March 2007	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08333.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08333.html</a>			
<b>Cuddly Comfort Pillows</b>	The pillows can contain small metal fragments in the fiber-fill as a result of a mechanical breakdown in the manufacturing process. The metal fragments can cause abrasions and cuts to consumers.	Consumers should immediately stop using the recalled pillows and return them to any Costco store for a full refund	The recalled Cuddly Comfort Pillows were sold in packs of two. Each pillow is 20" wide by 26" long, and they were sold in white, violet, blue, pink and yellow colors. Only pillows with Registration Number PA-27156(CA) are included in the recall. The Registration Number and the words "Sleep Innovations" are printed on the pillow's tag.	Sleep Innovations Inc., of West Long Branch, N.J.	February 2008 through June 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08596.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08596.html</a>			
<b>Indoor Lighting Fixtures</b>	A thermal protector could be missing from the lighting fixtures, posing a risk of overheating and fire	Consumers should immediately stop using the lighting fixtures and contact Lithonia Lighting to arrange for a free replacement fixture	The recalled fixture is a ceiling-mounted downlight. Model number LV3R is included in this recall and is printed on a UL label inside the light's housing	Lithonia Lighting, of Conyers, Ga	April 2007 through May 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08335.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08335.html</a>			
<b>Amsterdam Bicycles</b>	The interior alignment tabs of the bicycle's chainguard can be pushed against the chain causing it to derail, which poses a risk of injury to riders.	Consumers should immediately stop riding the recalled bicycle and bring it to an Electra Bicycle dealer for a free inspection and replacement chainguard part	This recall involves some Amsterdam model bicycles in the Classic 3, Original 3, Royal 8, and Sport 3 styles. The bicycles have an enclosed chainguard. "Electra" and "Amsterdam" are printed on the bicycle's frame and/or chainguard. Bicycles with frame numbers beginning with "F06" or "EL" or bicycles with chainguards marked "06/08" are not included in this recall. The frame number is located on the underside of the bottom bracket	Electra Bicycle Company, LLC of Vista, Calif.	January 2007 through June 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08337.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08337.html</a>			
<b>Dirt Devil Vacuum Power Brush Attachment Tools</b>	Plastic pieces inside the vacuum tool can break apart and be ejected, posing a laceration hazard to consumers.	Consumers should immediately stop using the recalled Dirt Devil accessory tool and contact the firm to receive a free repair kit	The recalled Dirt Devil Turbo Tool/Power Brush attachment was sold as an accessory with the following Dirt Devil vacuum models. Only vacuum tool accessories with date codes J7060 through J7365 and have a C-clip connector are included in this recall. The date code is located on the underside of the vacuum accessory. The Turbo Tool/Power Brush tools are about 6 ½ inches long by about 5 inches wide and come in a variety of colors that match the color of the vacuum. The housing of the tool was made in clear, red, green, or light blue with clear, light blue, dark blue, red, purple, or black turbine fans with matching brush rolls	TTI Floor Care North America, of Glenwillow, Ohio	April 2007 through April 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08339.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08339.html</a>			

<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>Reebok Studio Exercise Cycles</b>	The alloy cranks on the exercise cycles can break during use, posing a laceration and abrasion hazard to users	Consumers should stop using the recalled Studio Cycle immediately, and owners should contact Reebok International Ltd. to receive a discount on a model currently made by a licensee of Reebok.	The Reebok Studio Cycle is an upright exercise bike used primarily in fitness centers and other institutional settings. The recalled bicycle is black with silver cranks. The unit has an internal belt drive. The base of the bicycle is a single piece that is welded to the frame. The legs are two straight horizontal bars with rounded edges. There is a logo located on the side of the exercise cycle that shows a person riding a bicycle	Associates Incorporated (F.A.I.), under license from Reebok International Ltd., of Canton, Mass. Note: F.A.I. is no longer in	1997 through 2000	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08340.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08340.html</a>			
<b>Santorini Chairs</b>	The seat weld can fail and allow the chair to collapse, posing a fall hazard to consumers	Consumers should immediately stop using the chairs with side weld joints (see below) and return them to any Cost Plus or World Market store for a full refund or exchange. Chairs with rear weld joints (see below) are not included in this recall. To identify if the chair is part of this recall consumers should locate the seat base weld on the underside of the chair. Weld joints located on the sides of the seat are included in this recall.	This recall involves Santorini outdoor stacking chairs. The black metal chairs have vertical bars on the back and horizontal bars across the base	Cost Plus Inc., of Oakland, Calif.	January 2008 through April 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08342.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08342.html</a>			
<b>Classic Horseshoe Magnet</b>	The plastic coating on the magnets contains excessive levels of lead, which violates the federal lead paint standard.	Consumers should immediately take the classic horseshoe magnets away from children and contact Dowling Magnets to receive a free replacement horseshoe magnet.	This recall involves the Classic Horseshoe Magnets. The 6-inch tall horseshoe magnet has a red plastic coating on the "handle" end. Each "foot" of the magnet has an engraved "S" or and "N."	Dowling Magnets, of Sonoma, Calif	March 2003 through April 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08344.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08344.html</a>			
<b>U-shaped Magnets, Bar Magnets, Magnet Sets and Magnet Needle Sets</b>	The paint on the magnets can contain excess levels of lead, violating the federal lead paint standard.	Consumers should immediately stop using these recalled magnets and contact the firm to receive a free replacement	Large" and "Small" U-shaped Magnets: These magnets are in the shape of a "U" or horseshoe. One half of each magnet is painted red and is imprinted with the letter "N"; the other half is painted blue, and is imprinted with the letter "S".	Pacific Science Supplies Inc., of Bensenville, Ill	April 2000 through February 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08345.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08345.html</a>			

<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>Maxim Apogee and Maxim Pinnacle Dynamic Climbing Lines/Ropes</b>	The climbing lines can break, posing a serious fall hazard for climbers	Consumers should immediately stop using the recalled dynamic climbing lines and contact the manufacturer for a free replacement	Two types of climbing ropes have been included in this recall, the Maxim Apogee 9.1mm and Maxim Pinnacle 9.5mm. The Maxim Apogee 9.1mm is a 48 carrier climbing rope. The colors are yellow and black, and red and yellow. The model numbers are 3411-91 and 3415-91, with date codes 060801 thru 080601. The UPC codes are: 75396312299, 75396312298, 75396312301, and 75396312300. The Maxim Pinnacle 9.5mm is a blue 48 carrier climbing rope. The Model number is 3403-95, with date codes 070201 thru 080601. The UPC codes are 75396312292 and 75396312293. The date codes and the UPC codes are on the original packaging	New England Ropes, of Fall River, Mass.	August 2006 through June 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08346.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08346.html</a>			
<b>Cribs</b>	The cribs fail to meet the federal safety standards. The distance between the mattress support bracket in the lowest position and the top of the side rail in the highest position is less than the required 26 inches, posing a fall hazard to children who climb over the railing.	Consumers should stop using the cribs immediately and contact Mother Hubbard's Cupboards to receive instructions on how to re-install the support brackets to eliminate the hazard.	The recall includes the following wooden full-size cribs: "Enchantment" (model #210), "Hush a Bye" (model #215), "Once upon a time" (model #320) and "Rock a bye" (model #1900-350). Only date codes from 0306 through 0308 are included in this recall. "Mother Hubbard's Cupboards", the model number and date code are printed on a label located on the bottom inside of the right side.	Mother Hubbard's Cupboards, of Toronto, Canada	March 2006 through March 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08350.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08350.html</a>			
<b>Davenport Cribs</b>	The cribs fail to meet the federal safety standards for cribs. The cribs have a two mattress support system. The secondary mattress support, used for the lowest position, does not meet the full 26 inch minimum height in its lowest position, allowing children inside to crawl over the railing, posing a fall hazard.	Consumers should stop using the recalled cribs in the third lowest position, which uses the wooden mattress support, and contact Baby Appleseed to receive a repair kit. Consumers who are currently using the crib with the metal mattress support in the top or middle positions can continue to use the crib in those positions while awaiting a repair kit. (NOTE: Repair Kits will be available from the firm in mid-August 2008)	The recall includes Davenport crib models that begin with the model numbers 273-xxxx-xxxx and have manufacture dates on or before August 2007 printed on a label located on the right side of the lower inner panel of the crib. The recalled cribs have two mattress support systems-a metal one and a wooden one. Newer Davenport cribs with model numbers beginning with 244-xxxx-xxxx that have one mattress support are not included in the recall.	Baby Appleseed, of City of Industry, Calif.	December 2006 through September 2007	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08351.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08351.html</a>			
<b>DEWALT DC608 Cordless Brad Nailers</b>	The nailer can operate when the lock-off (safety) is in the locked position. Also, the nailer can operate when the trigger is not pulled and the contact trip is depressed. The unexpected ejection of a nail poses a serious injury hazard to consumers.	Consumers should immediately stop using the nailers and contact DEWALT for the location of the nearest service center to receive a free repair	This recall involves the DEWALT DC608 18 Volt Cordless 2" 18 Gauge Straight Brad Nailer with date codes 200728 through 200821. "DC608" is located on the right side of the magazine. The date code can be found on the underside of the handle, once the battery pack is removed. Units stamped with an "M" following the date code are not included in this recall.	DEWALT Industrial Tool Co., of Towson, Md	October 2007 through May 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08352.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08352.html</a>			

<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>Chicago Electric Halogen Work Lights</b>	The halogen work lights can overheat and melt, and pose a risk of fire and electrical shock to consumers	Consumers should immediately stop using the halogen work lights and contact Harbor Freight Tools for a full refund.	The halogen work lights are 500 watts. Model number 30858 is included in this recall. The lamp measures 7 inches wide x 5 ½ inches high and is mounted on a yellow frame. "UL Listed E163392" and "Work Light 8F95" is printed on a sticker on the back. The model number is printed on the light's packaging	Harbor Freight Tools, of Camarillo, Calif.	February 2006 through March 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08353.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08353.html</a>			
<b>KéO Bicycle Pedals</b>	The steel axle inside the pedal can break, posing a fall hazard to cyclists	Consumers should immediately stop using the recalled bicycle pedals and return them to any authorized Look Cycle dealer, or contact Look Cycle USA to arrange for shipping and free repair.	The recalled bicycle pedals were sold separately from bicycles. Pedal models include KéO Classic, KéO Sprint, KéO HM and KéO Carbon. The model name is printed in white on the side of the pedal. Date codes between January 2004 and December 2005 are included in this recall. The date code for the KéO Classic, Sprint and Carbon pedals is on a dial stamped onto the pedal. The date code for the KéO HM is on the bottom of the pedal, with the letters A through L corresponding to the month, and the numbers 4 and 5 indicating 2004 or 2005. "T" pedals are not included in this recall.	Look Cycle USA, of San Jose, Calif.	January 2004 through July 2007	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08354.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08354.html</a>			
<b>Perfect Flame Double Lid Four Burner Gas Grills</b>	The cooking chamber of the grill can melt and/or ignite, posing a risk of fires and burn injuries to consumers.	Consumers should immediately stop using the recalled grills, disconnect the propane tanks, and return the grills without the propane tanks to any Lowe's store to receive a full refund.	This recall involves Perfect Flame brand grills, Model GAC3615 four burner LP gas grills. The grill has two lids. "Perfect Flame" is printed on the larger lid. The model number, serial number, and date code are printed on a label on the right side cart frame panel.	Lowe's Home Centers, Inc., of North Wilkesboro, N.C. and Lowe's HIW, Inc., of	October 2007 through July 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08359.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08359.html</a>			
<b>Pendant-Style Ceiling-Mounted Indoor Light Fixtures</b>	The ceiling-mount assembly that supports the light fixture can fail, causing the fixture to unexpectedly fall and injure consumers.	Consumers should carefully remove the glass from the fixture and contact Progress Lighting to schedule a free inspection and replacement	The recall involves the following models of pendant-style ceiling-mounted light fixtures: P3601-09, P3602-09, P3603-09, P3603-09EXP, P3685-09, P3685-09EXP, P4260-09, P4261-09, P4261-09EXP and P4262-09. The product number is located inside the canopy located flush with the ceiling. The fixtures have frosted white glass and a brushed aluminum finish.	Progress Lighting, of Greenville, S.C.	January 2005 through May 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08360.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08360.html</a>			

<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>Signature Gourmet™ and Crofton® Personal Blenders</b>	While placing the cup on or off the base of the blender, the blender can be inadvertently turned on, activating the blade. This can pose a serious laceration hazard to consumers.	Consumers should stop using the recalled blenders immediately and call Atico International USA for instructions on returning the product for a full refund.	This recall involves the Signature Gourmet™ (item number W14A3691) and the Crofton® (model number SB-19) personal blenders. The blenders are white and have 3 components parts – a base containing a power button, a blade assembly, and a blending cup. Signature Gourmet™ or Crofton® is printed on the front of the base of the unit. “SB-19” or “W14A3691” is located on a label at the bottom of the unit.	Atico International USA Inc., of Fort Lauderdale, Fla. (for the Crofton® model) and East West Distributing Co., of Deerfield Ill. (for the Signature Gourmet™ model)	July 2006 through March 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08361.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08361.html</a>			
<b>Sure-Lite™ and “AtLite™” Exit and Emergency Lights</b>	The lights can malfunction and not stay illuminated in the event of a power failure. This could result in a failure to provide adequate lighting to guide building occupants to an exit in an emergency.	Cooper Lighting is contacting customers directly and is providing a free replacement product.	The recalled emergency and exit lights are installed in commercial buildings such as hotels and office buildings.	Cooper Lighting Inc., of Peachtree City, Ga.	September 2007 through June 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08598.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08598.html</a>			
<b>Flame Weeders</b>	The two-piece brass control valve can separate between the flame weeder and the propane tank and allow propane to leak from the tank. This poses fire and burn hazards to consumers.	Consumers should immediately stop using the flame weeders and return them to the store where purchased or call Gardener’s Supply Co. for a full refund including any shipping costs. Gardener’s Supply Co. is directly contacting consumers who purchased the recalled flame weeders.	The recalled flame weeders are used to burn weeds. The weeders have a long silver colored metal tube with a blue plastic handle which is attached by a two-piece brass valve to a 1 lb. propane tank.	Gardener’s Supply Co., of Burlington, Vt.	March 2008 through July 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08600.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08600.html</a>			
<b>Amsterdam Bicycles</b>	The interior alignment tabs of the bicycle’s chainguard can be pushed against the chain causing it to derail, which poses a risk of injury to riders	Consumers should immediately stop riding these bicycles and contact Electra Bicycle to determine if his/her bike is included in this recall. Consumers with a recalled bike can bring it to an Electra Bicycle dealer for a free inspection and replacement chainguard part.	This recall involves some Amsterdam model bicycles in the Classic 3, Original 3, Royal 8, and Sport 3 styles. The bicycles have an enclosed chainguard. “Electra” and “Amsterdam” are printed on the bicycle’s frame and/or chainguard. Bicycles with frame numbers beginning with “EL” or bicycles with chainguards marked “06/08” are not included in this recall. The frame number is located on the underside of the bottom bracket	Electra Bicycle Company, LLC, of Vista, Calif	January 2007 through June 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08365.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08365.html</a>			

<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>H2O Portable Hand Held Steam Cleaners</b>	Steam can escape from the handle and trigger of the steam cleaner, posing a burn hazard to consumers.	Consumers should immediately stop using the recalled steam cleaners and contact Thane to receive a \$30 coupon for the purchase of another Thane product or to receive a free replacement steam cleaner. Thane has directly contacted consumers who received the steam cleaners.	The recalled portable hand held steam cleaners are white and dark gray. "H2O" and "M" are printed on the steam cleaners. Model number YQ3888 and the "produce code" are printed on a label on the underside of the units. This recall only includes steam cleaners with "produce codes" from 071025 through 080324.	Thane International Inc., of La Quinta, Calif	December 2007 through May 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08601.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08601.html</a>			
<b>Electrical Wire Splices</b>	When crimped, the splice can fail to hold the wires adequately together, posing a shock and fire hazard to consumers.	Consumers should immediately stop using products that contain the recalled butt splices and contact the firm for free replacement splices	The recalled butt splices are used to connect electrical wires to one another. They are typically used for wiring small electrical appliances, like audio equipment, or in automotive applications. The splices are yellow insulated vinyl and measure about one inch long and ¼ inch wide. They were intended for use with 12-10 AWG wire. 12-10 is stamped on the side of the splices. Model numbers 10-126, or 21-126, and Gardner Bender are printed on the product's packaging. They were sold in packages of 8 or 50.	Gardner Bender, of Milwaukee, Wis.	June 2005 through April 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08367.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08367.html</a>			
<b>Wolf SL Carbon Fiber Bicycle Forks</b>	The forks steerer can break during normal use, causing the rider to lose control, fall and suffer serious injuries	Consumers should immediately stop using bicycles equipped with the recalled forks and contact their authorized Cervélo dealer to have a free replacement fork installed.	The recalled forks have a clear coating over black painted carbon fiber, with the words "Wolf Superlite" and related logo just below the crown on each fork leg, and the letters "SL" on each leg above the fork blade dropouts. There is a True Temper CRT™ logo on the inside of both fork legs. The recalled forks could have been included on the following bicycle models: R3, R3 SL, Soloist Carbon, Soloist Carbon SL, and certain P3 Carbon framesets and complete bicycles	Cervélo SA, of Switzerland	November 2005 through July 2007	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08368.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08368.html</a>			
<b>Light Commercial Heat Recovery Ventilators</b>	The motors in these units can overheat, posing a fire hazard to consumers.	Consumers should immediately turn off the ventilator, disconnect it from the power supply, and contact Venmar CES to schedule a technician to install a free repair.	Light Commercial Heat Recovery Ventilators are designed to exchange air between the inside and outside of a building or home in order to provide fresh air.	Venmar CES Inc., of Saskatoon, Canada	January 1991 through July 2007	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08369.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08369.html</a>			
<b>Power Light Modules</b>	Internal wiring in the module's circuit boards is incorrectly installed, posing a risk of an electrical fire and burn hazards to consumers.	Consumers should immediately stop using the recalled power light modules and contact GCI Technologies to request a repair or replacement	This recall involves Gemini brand power light modules used in DJ rack systems. Models included in this recall are PL-01 and PI-02. The model numbers are printed on the front of the module, near the power switch. Models included in this recall have an ETL logo on the back panel	GCI Technologies Corp., of Edison, N.J.	July 2004 and September 2007	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08371.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08371.html</a>			

<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>Kenmore and Kenmore Elite Coffee Makers</b>	The wiring in the coffee maker can overheat, posing burn and fire hazards to consumers	Consumers should immediately stop using the coffee makers and take them to their nearest Sears or Kmart store to obtain a free replacement coffee maker	This recall involves 12-cup Kenmore coffee makers sold in black, white, and red with the following model numbers: 100.80006 (black), 100.81006 (white), and 100.82006 (red). The recall also involves 12-cup Kenmore Elite coffee makers with thermal carafe (model number 100.90007) and 14-cup Kenmore Elite coffee makers (model number 100.90006). The model number can be found on the bottom of the unit. There is a Kenmore or Kenmore Elite logo on the front bottom of the maker.	Sears, Roebuck and Co., the great indoors and Kmart Corp., of Hoffman Estates, Ill.	August 2007 through April 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08372.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08372.html</a>			
<b>Car Chargers Used with Power System Plus 3 Million Candlepower Spotlights</b>	The car charger is incompatible with the spotlight's battery, which can cause it to overcharge inside of a vehicle and pose a fire or burn hazard to consumers	Consumers should immediately stop using the recalled car charger and contact IMS for information on how to receive a free replacement car charger. Consumers can continue to use the spotlights without the car charger.	The recalled 12V DC car charger was sold with the Power Systems Plus/UST 3 Million Candlepower Spotlight with model number HSLR30S. The spotlight is black and blue and has a sticker on each side that reads "3 Million Candle Power." "HSLR30S" is printed on the instruction manual and on the packaging.	International Merchandising Service Inc. (IMS), of Fullerton, Calif.	October 2007 to June 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08374.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08374.html</a>			
<b>Packaged Terminal Air Conditioner/Heat Pump (PTAC) Units</b>	The PTAC's power cords can overheat, posing a burn or fire hazard	Consumers should contact Goodman to receive a free replacement power cord. Commercial and institutional owners will be contacted directly and will install the power cord.	The recall includes 5.0 kW Amana-brand and Energy Knight-brand PTAC units with model numbers PTxxx3x50xx and EKT-xxx150xx and serial numbers 0702112056 through 0804237539. The model and serial numbers are located on the control board plate found under the PTAC unit's front cover	Goodman Company L.P., of Houston, Texas	February 2007 through June 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08602.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08602.html</a>			
<b>Indoor Lighting Fixtures</b>	The glass reflector can separate from the fixture and fall, posing a risk of injury to consumers below the fixture.	Consumers should inspect the fixtures immediately and take down any units with loose glass. Consumers should contact Lithonia Lighting to arrange for a free replacement.	The recall involves the Hi-Bay Indoor High-Intensity Discharge (HID) Fixtures, model numbers PG16A and PG21A. The fixture is intended for high-mounting heights (at least 20 feet above floor level) and is used in retail, warehouse and heavy manufacturing locations. The fixture's housing is made of die-cast aluminum	Lithonia Lighting, of Conyers, Ga.	January 2007 through May 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08375.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08375.html</a>			
<b>Illuminator Polariscopes 415000 and 415</b>	The polariscopes can have a ground wire missing, posing a risk of electrical shock to the user.	Consumers should immediately stop using the recalled product and contact GIA Instruments to schedule a free retrofit of the Polariscopes with a ground wire. GIA is notifying all consumers directly.	The recalled polariscopes are white in color with model number 415000 or 415 printed on the underside of the instrument. A polariscopes is an instrument used by gemologists to assist in gem identification.	GIA Instruments, of Carlsbad, Calif	January 1996 through June 2007	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08603.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08603.html</a>			

<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>Countertop Water Dispensers</b>	The internal heating element could overheat and drop molten metal through ventilation openings in the water dispenser's base onto the countertop, posing a fire hazard. The internal heating element also poses a shock hazard to consumers who touch it through the vents.	Consumers should stop using the recalled water dispensers immediately and contact Greenway Home Products to receive a free repair	The recalled countertop water dispensers include the following Vitapur, Greenway and Polar models. They dispense hot or cold water and use three or five gallon water bottles. The model name is printed on the front of the dispenser's base. Model and serial numbers are printed on a white label on the back of the dispenser's base. File number 218326 is printed on a silver sticker on the back of the dispenser's base.	Greenway Home Products, of Northwood, Ohio	June 2006 to November 2007	<a href="http://www.cpsc.gov/cpscpub/prerel/prhtml08/08376.html">http://www.cpsc.gov/cpscpub/prerel/prhtml08/08376.html</a>			
<b>Yayita Baby Hammocks</b>	The hammock can flip over, posing a serious fall hazard and strangulation hazard to infants who get entrapped in the seat's restraint straps while upside down.	Consumers should immediately stop using the baby hammock and contact FlagHouse to receive a full refund, or credit toward the purchase of another product	The recalled baby hammock is cream-colored canvas and hangs from a wooden pole. The hammock measures about 29 x 43 inches. It has three restraint straps with red buckles and is attached to a cushioned pad for the infant. A mounting fixture, also called a fixing set, is sold with the hammock. "La Siesta" is printed on a tag located below the restraint straps. Model number YABP-1 is printed on a white tag sewn into the hammock's side seam.	FlagHouse Inc., of Hasbrouck Heights, N.J.	September 2007 through August 2008	<a href="http://www.cpsc.gov/cpscpub/prerel/prhtml08/08604.html">http://www.cpsc.gov/cpscpub/prerel/prhtml08/08604.html</a>			
<b>Portable Garden Hose Reel Carts and Wagons</b>	The tires on the portable garden hose reel can explode while being inflated, posing an injury hazard to consumers.	Consumers should not inflate tires on the portable hose carts and contact Rapid Reel® for free replacement tires.	This recall involves the Rapid Reel® portable garden hose reel carts and wagons. The cart has two tires and the wagon has four. The tires have a white plastic rim and a steel ball bearing hub or a black plastic bearing hub.	Eley Corporation, dba Rapid Reel of Lincoln, Neb.	April 2005 through March 2006	<a href="http://www.cpsc.gov/cpscpub/prerel/prhtml08/08384.html">http://www.cpsc.gov/cpscpub/prerel/prhtml08/08384.html</a>			
<b>Deda Forza Bicycle Handlebar Stems</b>	The top of the bicycle handlebar stem can crack and cause the rider to lose control, posing a crash hazard	Consumers should stop using the bicycles equipped with the recalled Deda Forza handlebar stems and return them to the place of purchase to receive a free replacement handlebar stem	The recall involves bicycles with Deda Forza black carbon fiber handlebar stems in gloss finish. "Deda Forza" is printed on the handlebar stem. Deda Forza black carbon fiber handlebar stems in matte finish are not included in this recall.	Deda Elementi S.r.l., of Italy	January 2008 through June 2008	<a href="http://www.cpsc.gov/cpscpub/prerel/prhtml08/08385.html">http://www.cpsc.gov/cpscpub/prerel/prhtml08/08385.html</a>			
<b>MasterForce 3.6-volt Cordless Screwdrivers</b>	The battery can overheat and ignite during charging, posing a fire and burn hazard to consumers. There is no protective device on the lithium battery to prevent overheating.	Consumers should immediately stop using the screwdrivers and return them to any Menards store for a free replacement or refund.	The recalled cordless screwdrivers are green and gray in color. "MASTERFORCE" is printed on the top of the tool. "LITHIUM-ION TECHNOLOGY" and "241-0717" are printed on the handle.	Menards, of Eau Claire, Wisc	April 2007 through May 2008	<a href="http://www.cpsc.gov/cpscpub/prerel/prhtml08/08388.html">http://www.cpsc.gov/cpscpub/prerel/prhtml08/08388.html</a>			
<b>Action Baby Carriers</b>	The baby carrier's chest strap can detach from the shoulder straps, posing a fall hazard to the baby.	Consumers should immediately stop using the carrier in the positions that require the use of the chest strap and contact Optave to receive free replacement straps.	The recalled carriers were sold under the "Action Baby Carrier" brand name. The carriers are sold in various colors and patterns: blue, brown, green, "so square", "the larrisa" and "spring breeze."	Optave Inc., of Alpena, Mich	May 2008 through June 2008	<a href="http://www.cpsc.gov/cpscpub/prerel/prhtml08/08389.html">http://www.cpsc.gov/cpscpub/prerel/prhtml08/08389.html</a>			

<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>Wolf Appliance Gas Ranges</b>	Delayed ignition of gas in the 18-inch oven can cause a flash of flames to be projected at a consumer when the range door is opened, posing a burn hazard to consumers.	Consumers should immediately stop using the recalled gas range 18-inch oven and contact the manufacturer to schedule a free, in-home repair. The large oven and all cooktop burners are not affected and may be used.	This recall involves the following Wolf Appliance 48-Inch gas ranges with model numbers: P48, PS48 and R48. The gas ranges are stainless steel with a double oven. A "Wolf" appliance logo is on the front of the larger oven door.	Wolf Appliance Inc., of Madison, Wis.	January 1998 through June 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08391.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08391.html</a>			
<b>Certain VAIO TZ-series Notebook Computers</b>	Irregularly positioned wires near the computer's hinge and/or a dislodged screw inside the hinge can cause a short circuit and overheating. This poses a burn hazard to consumers	Consumers should stop using the recalled notebook computers immediately and contact Sony to determine if their notebook is affected. The firm will arrange for an inspection and repair, if needed	The recalled notebook computer models are the VAIO VGN-TZ100 series, VGN-TZ200 series, VGN-TZ300 series and VGN-TZ2000 series. The computers' screen size is about 11.1" measured diagonally. Not all units are affected; consumers should contact Sony to determine if their unit is included in the recall.	Sony Electronics Inc., of San Diego, Calif.	July 2007 through August 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08392.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08392.html</a>			
<b>Titan DIN 1st Stage Scuba Regulators and Titan/Conshelf DIN Scuba Adaptors</b>	Over-tightening of the DIN retainer by a technician during installation can result in the retainer breaking under pressure, a rapid escape of air from the scuba cylinder, and the regulator detaching from the scuba cylinder. This poses a drowning hazard to divers.	Consumers should immediately stop using the recalled diving regulators and DIN adaptors and return them to any authorized Aqua Lung dealer for a free replacement DIN retainer.	The recalled regulators have a brass DIN retainer manufactured prior to June 2006. The recalled Aqua Lung Titan Din 1st Stage regulators have serial numbers lower than 6062501 stamped on the side of the regulator's body. Recalled Titan/Conshelf DIN adaptors are marked "300 BAR MAX" on the side of the part. DIN adaptors marked "300 BAR MAX1" are not included in this recall	Aqua Lung USA, of Vista, Calif.	January 1997 through September 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08393.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08393.html</a>			
<b>Zebra Rug</b>	The rugs do not meet the federal flammability standard for small rugs and do not have the required flammability warning label.	Consumers should contact JLA Home to receive a warning label to be affixed to the backside of the rug, or consumers can contact JLA home for instructions on returning the rug for a full refund	The recalled rug measures 30" x 54" and has a black-and-white zebra skin design. The rug was sold under J.C. Penney item number MF728-1050, which is located on the product's packaging.	JLA Home, of Plano, Texas	December 2007 through July 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08605.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08605.html</a>			
<b>Gas Boilers</b>	The pressure switch could have an internal defect that could fail to shut down the boilers under vent or air inlet blockage. This switch defect could allow the boilers to produce excessive levels of carbon monoxide, posing a risk of carbon monoxide poisoning to consumers	Consumers who have not already been contacted, should contact their installer immediately for a free safety inspection and repair, if necessary.	This recall involves the DE and PSC II Gas Fired Cast Iron Boilers with the Endura Plastics Model ES2035 pressure switch used for home heating and domestic hot water heating. The boilers were available in either natural or LP gas. The boiler rating label is located on the top jacket panel on Series PSCII models and the left side jacket panel on the Series DE models. The label includes the model and serial number	PB Heat LLC, of Bally, Pa.	May 2007 through July 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08397.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08397.html</a>			
<b>John Deere Gator XUV 620i Utility Vehicles</b>	The fuel tank can leak from a gap in the seam at the base of the filler neck, posing a fire hazard	Consumers should stop using the recalled utility vehicles immediately and contact any John Deere dealer to schedule a free inspection and repair. Keep fuel tank below half full until the repair is made. Registered owners were sent direct mail notification of this recall.	The recalled utility vehicle is Model 620i. The model number is painted on the side of the vehicle	Deere & Company, of Moline, Ill.	April 2008 through August 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08606.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08606.html</a>			

<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>Children's Metal Water Bottles</b>	The sip top on the water bottles can pull off, posing a choking hazard to young children	Consumers should take the recalled water bottles away from children immediately and return them to any Pottery Barn Kids' store for a full refund. If purchased through the catalog or online, contact Pottery Barn Kids to receive a full refund	The metal water bottles are about 9 inches tall and have a black rubber pull up sip top.	Pottery Barn Kids, of San Francisco, Calif.	January 2007 through August 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08399.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08399.html</a>			
<b>MacGregor Folding Soccer Goals, Mitre Folding Soccer Goals</b>	The fixed knot flexible openings in the soccer goal net can pose a head and neck entrapment or strangulation hazard to young children	Consumers should stop using the recalled soccer goal nets immediately and return them to Regent Sports to receive a free replacement net	Both soccer goals have a foldable white frame with a white net that is attached by Velcro strips. When upright, the MacGregor goal measures 6 feet wide by 3 feet high and the Mitre net measures 8 feet wide by 6 feet high. Each has a recalled net with squares measuring 5 inches on each side. The MacGregor soccer goal has model number 97236 printed on the assembly instructions and UPC code number 029807972365 printed on the net's packaging. The Mitre soccer goal has model number 89186 printed on the assembly instructions and UPC code number 029807891864 printed on the net's packaging. Nets manufactured after April 2007 with 4 inch by 4 inch square openings are not included in the recall.	Regent Sports Corporation, of Hauppauge, N.Y.	May 2002 through May 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08400.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08400.html</a>			
<b>Simplicity Brand Drop Side Cribs</b>	Due to sizing problems with the crib's hardware, the drop side can come off the tracks. When the drop side detaches or partially detaches, it creates a hazardous gap, which can lead to infant entrapment and suffocation	Consumers should immediately stop using the recalled cribs and find an alternative, safe sleeping environment for their baby. Consumers should return the recalled crib to the place of purchase for a refund or store credit. SFCA Inc., of Reading, Pa. is working with retailers to carry out this recall program	This recall of Simplicity drop side cribs involves models that used a different style of hardware from those cribs recalled in September 2007. The recalled model numbers include: 8620, 8745, 8748, 8755, 8756, 8778, 8810, and 8994. The recalled drop side cribs have a date code, which can be found on a label on the headboard under the mattress support, which ends in 05DH, 05GB, 06DH, 06GB, 07DH or 07GB (examples: 1806 DH or 0507 GB). The recalled model names include: Aspen and Crib N Changer Combo, Gabrielle, Camille, Providence and Shenandoah. Only the brand name "Simplicity" can be seen on the label on the headboard	Simplicity Inc., of Reading, Pa. (this company is no longer in business)	January 2005 through August 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08401.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08401.html</a>			
<b>Power Cords</b>	The power cord wires are significantly undersized and allow incorrect insertion of the power plug, posing a risk of fire and/or shock to consumers.	Consumers should immediately stop using the recalled power cords and contact the firm for a full refund.	The recall involves 2-Ft., three outlet power cords. The power cord is orange in color and packaged in a counterfeit yellow and green cardboard sleeve. The packaging indicates the power cord is a "12 Gauge Extra Heavy Duty" type. Model number T-4145 is printed in front and back of the packaging, which is indicated in the picture below.	DCI LLC, d/b/a Hanashop, of Olive Branch, Miss	November 2006 through April 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08607.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08607.html</a>			

<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>Cooks Essentials Deep Fryers</b>	The fryers can overheat, posing a burn hazard	Known purchasers were mailed instructions on obtaining a full refund. Consumers who have not received instructions should contact QVC for refund instructions	The recalled fryers include QVC Cook Essentials 3 Liter Stainless Steel Deep Fryers with three baskets. The fryers were sold as item number K14942. Model number F1053Q is printed on a sticker on the bottom of the fryers	QVC Inc., of West Chester, Pa.	April 2008 through May 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08609.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08609.html</a>			
<b>Harry Potter Bookends</b>	The paint on the bookends contains excessive levels of lead, violating the federal lead paint standard.	Consumers should immediately take the recalled bookends away from children and return them to Giftco for a refund.	This recall involves poly-stone bookends painted and shaped in the characters of the Harry Potter book series. Bookend characters include Harry Potter, Hedwig and Hermione, and Crookshank	Giftco Inc., of Vernon Hills, Ill.	June 2004 through January 2006	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08404.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08404.html</a>			
<b>Gotham Compact Fluorescent Downlights (Recessed Ceiling Lights)</b>	The relay on the backup battery of the lights could be programmed incorrectly and prevent the lights from functioning in an emergency.	Consumers should inspect the fixtures immediately and contact Gotham Lighting to receive a repair for the light fixture.	Only Gotham Compact Fluorescent Downlights sold with the optional backup battery pack are included in the recall. The lights are recessed ceiling lights that were manufactured between November 1, 2007 and July 31, 2008.	Gotham Lighting, of Conyers, Ga.	November 2007 through July 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08405.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08405.html</a>			
<b>SmartSpace™ Papasan Chairs</b>	The chairs were sold without a warning label instructing consumers to lock the chair's legs before sitting. This poses a fall hazard to consumers.	Consumers should immediately stop using the chair until a warning label, instructing consumers to engage the legs in the locked position before use, has been obtained from Jo-Ann Fabric and Craft Stores	This recall involves the SmartSpace™ Papasan chair. The silver metal frame chair has a circular fabric seat that sits on a 10-inch-tall base. The fabric seat used with the papasan chairs were sold in purple, pacific, lime yellow and gray. A hangtag on the chair reads "Smartspace Papasan Chair – 1 piece."	Jo-Ann Stores Inc., of Hudson, Ohio	June 2008 through September 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08406.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08406.html</a>			
<b>TV Stands</b>	The stability of the stands does not meet industry standards to prevent TV tip-over, posing a risk of injury or death to consumers.	Consumers should immediately remove the TV from the stand and contact Studio RTA to receive a free repair kit	"E Series" Model 060331: The product consists of two glass shelves, a lower shelf made of metal, and black leg and frame components. "Fierro" Model 402875: This product was sold exclusively by Best Buy. The product consists of three glass shelves with black leg and frame components. "Madison DLP" Model 060176: The product consists of three glass shelves with dark wood grain finish frame components, black legs, and a black fiberboard back panel. "Madison 3000" Model 060090: The product consists of three glass shelves with dark wood grain finish frame components, black legs, and a metal mesh back panel.	Studio RTA, of Pico Rivera, Calif	May 2004 through August 2008	<a href="http://www.cpsc.gov/cpscpub/prerele/prhtml08/08408.html">http://www.cpsc.gov/cpscpub/prerele/prhtml08/08408.html</a>			

<u>Name of Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
<b>Razor® Dirt Quad Electric Powered Ride-On Vehicles</b>	The control module for the throttle can fail and cause the electric ride-on vehicle to unexpectedly surge forward, posing a risk of injury to the user or a bystander	Consumers should immediately stop using the product and contact Razor for a free replacement controller	This recall involves Razor® Dirt Quad electrically powered ride-on vehicles. Product ID numbers included in the recall begin with 103110-01 or 103110-02. The product ID numbers are located on the bar code affixed to the right step of the vehicle, on the charger and on the retail packaging. Product ID numbers beginning with 103110-03 or later are not included in this recall	Razor USA LLC, of Cerritos, Calif.	August 2006 through September 2007	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08410.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08410.html</a>			
<b>Jack Lift Tools and Kits</b>	The jack lifts can have threads stripping or the nuts breaking, resulting in the shaft slipping and the mower falling from its stand-up position. This could cause serious personal injury to the consumer or property damage.	Consumers should immediately stop using the jacks and contact their local service dealer to have their lawn mowers repaired at no charge	The recalled jacks are used for lifting the lawn mower during service or maintenance. Two versions of this jack model have been manufactured. Version number one was made with a nylon nut and version number two was made with a sintered bronze nut. These recalled jacks were sold separately and on Charger, JAZee and Boss riding lawn mowers	Shivvers Manufacturing Inc., of Corydon, Iowa	May 2007 through June 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08611.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08611.html</a>			
<b>General Electric Toasters</b>	An electrical short circuit can occur between the heating element and the bread cage, posing a fire and electrical shock hazard to consumers	Consumers should immediately stop using the recalled toasters and return them to any Wal-Mart for a full refund or replacement toaster	The recalled toasters have a chrome steel body, a black plastic base and controls with either two or four openings in the top. The GE logo is located on the front of the toasters just above the controls. Model numbers 169115 and 169116 are included in this recall. The model number is printed on the bottom of the toasters.	Wal-Mart Stores Inc., of Bentonville, Ark.	September 2007 through July 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08413.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08413.html</a>			
<b>“KVIBY” Chests</b>	The glass drawer knobs on the chest can break either during assembly or in use, posing a laceration hazard to consumers.	Consumers should protect their hands and carefully remove the glass knobs. Contact IKEA to receive free replacement knobs and screws by mail	The recalled KVIBY Chest is white with 4 drawers and 6 glass knobs. The recall includes chests with article number 201-080-90 and a date stamp of 0817 (first two digits indicate the year; the second two digits indicate the week) or earlier. The article number and date stamp are located on a label attached to the underside of the chest. KVIBY chests with a date stamp of 0818 and later have improved replacement knobs and screws and are not included in the recall.	IKEA Home Furnishings, of Conshohocken, Pa.	August 2007 through July 2008	<a href="http://www.cpsc.gov/cpscpub/prereel/prhtml08/08414.html">http://www.cpsc.gov/cpscpub/prereel/prhtml08/08414.html</a>			