

**Toy Recalled Products Transmittal Form,
Third Quarter 2008**

Name of Product	Hazard	Remedy	Description	Distributor	Market Date	Web Link	Present	Not Present	Abated
Redcat Racing FM Remote Controlled Vehicles	The remote control unit can lose its signal, causing the toy vehicle to lose control, posing a risk of injury to the user or bystanders	Consumers should immediately stop using the product and contact Redcat Racing for a replacement remote control	The model name and numbers are located on the body of the vehicle or on the retail packaging	Redcat Racing Co., of Phoenix, Ariz.	March 2007 through April 2008	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08318.html			
Bright Starts Ring Rattles	The tip of the rattle's antenna, which is attached to a bee figure, can detach and pose a choking hazard to small children.	Consumers should immediately take the recalled rattles away from small children and contact Kids II to receive a free replacement rattle.	The soft toy rattle is a bee with a yellow head, ring-shaped green body, blue/green wings and purple/red antennas. Model number 8534 and date code PA8 are printed on a sewn-in label on the bee's head.	Kids II Inc., of Alpharetta, Ga	January 2008 through June 2008	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08343.html			
Wooden Toys	The recalled toys contain small parts or can break into small parts, posing a choking hazard. The recalled rattles violate the federal rattle standard. Some of the toys also have a string longer than 12 inches, which can pose a strangulation hazard to young children	Consumers should immediately take the recalled toys away from children and contact Earthenree for exchange or refund	This recall involves a variety of wooden toys including egg shakers (maracas), pull toys, rattles, and trains. The toys are painted glossy red, orange, green, brown, yellow or natural wood.	Earthenree of Kirkland, Wash	December 2007 through May 2008	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08347.html			
Learning Pots & Pans™ Toys	Missing screws in the blue toy pan can cause the clear plastic cover to come loose and release small balls, presenting a choking hazard to young children.	Consumers should immediately take these recalled toys away from children and examine the bottom of the blue pan. The pan should contain six screws. If all six screws are installed, no further action is necessary. If any screws are missing, the consumer should contact Fisher-Price to arrange for the return of the blue pan for a replacement.	This recall involves Learning Pots and Pans™ toy sets with stackable pots and pans, a lid and shape-sorting blocks. The toys have light and sound features that operate on three AA batteries. Model number G6685 is located on the bottom of the blue pan	Fisher-Price, of East Aurora, NY	October 2007 to August 2008	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08362.html			
Taggies™ Strollin' Along Stroller Activity Bars	The shiny material on the elephant's ear on the activity bar can detach, posing a choking hazard to young children.	Consumers should immediately stop using the activity bars and contact International Playthings for a free replacement toy.	This recall involves the Taggies™ Strollin' Along stroller activity bars. The multicolored, fabric, and plastic activity bars feature a yellow giraffe, a purple hippo and a blue elephant attached to a 12" long elliptical base with straps that attach to a stroller. The Taggies™ and Earlyyears® logos are located on woven and satin labels sewn into the seam on the lower left front of the activity bar.	International Playthings Inc., of Parsippany, N.J.	February 2007 through July 2008	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08373.html			
Wooden Puzzles, Infant Rattles, Pacifier Holders, and Stroller Toys	The wooden rattles, pacifier holders, and stroller toys contain small pieces including glued on mirrors and/or prisms that can detach, posing a choking hazard to infants. The head of the ladybug puzzle pieces also poses a choking hazard	Consumers should immediately take the recalled puzzles, rattles, pacifier holders and stroller toys away from children and contact Habermaass to receive a free replacement product or a full refund.	The puzzles, rattle toys, pacifier holders, and stroller toys are wooden and are described in the chart below. "HABA" is printed on them.	Habermaass Corp. Inc., of Skaneateles, N.Y	January 2002 through August 2008	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08380.html			

Name of Product	Hazard	Remedy	Description	Distributor	Market Date	Web Link	Present	Not Present	Abated
Bonne Bell Children's Cosmetics Accessory Bags	The metal clasps on the handle of the accessory bags contain excessive levels of lead, which is toxic if ingested and can cause adverse health effects.	Consumers should immediately take the recalled accessory bag away from children and contact Bonne Bell for a replacement bag.	The recalled accessory bags are made of plastic and have a zipper and carrying handle. The bags come with an assortment of cosmetic products, which are not part of this recall. The model name and UPC numbers are located on the hangtag.	Bonne Bell Co., of Lakewood, Ohio	September 2007 through August 2008	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08382.html			
Wood Abacus	The wooden rods on the abacus can detach, posing a choking hazard to young children	Consumers should take the abacus away from children immediately and contact LTD Commodities for instructions on receiving a product credit.	The recalled wood abacus is a multi-sided activity center that has a chalkboard, movable block letters with pictures, sliding shapes, a fun maze with gears, and a blue and yellow clock on the side of the activity center with two pink moving hands. Product code E7A is printed on the packaging near the UPC bar code	LTD Commodities LLC and ABC Distributing, of Bannockburn, Ill.	December 2006 through February 2008	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08608.html			
Toy Police Cars	The red paint on the toy cars contains excess levels of lead, violating the federal lead paint standard	Consumers should immediately take this toy away from children and return it to the store where purchased for a refund	This recall involves toy police cars with a friction function. When the toy car is pushed forward, the car builds momentum. When released, the car moves forward on its own. The cars were sold in red/white and purple/white color combinations. The cars measure 8 inches by 4 inches by 4 ½ inches. Item number TF820 is printed on the product's packaging.	TCB Imports, of Vernon, California	May 2008 through August 2008	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08412.html			
Toy Boats	The paint on the recalled toy boats contains an excess level of lead, violating the federal lead paint standard	Consumers should immediately take the recalled toys away from children and contact Buzz's Boatyard for a refund or an exchange	This recall involves two models of tin Pop Pop toy boats. Models included in the recall are the 13-inch "Titanic" and the "Hut" Pop Pop boats.	Buzz's Boatyard, of New Smyrna Beach, Fla.	April 2007 to November 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08415.html			